



Report No.: 4397049.01-23

Report Date: 2022-12-15

This is to supersede our report 4397049.00-23 issued on 2022-12-15

Inspection report

Client :	SOTECH INTERNATIONAL	Tel:	+334 83454732	Fax:	+ 48 939357
Attn:	Alain / Michele	Supplier:			
Inspection Date:	2022-12-12~14	<input type="checkbox"/> 1 st /2 nd Re-inspection (Previous Report No.)			
Product Description:	Rice cooker				
Manufacturer Name:					
Manufacturer Location:					
Manufacturer Contact:					
Service Required:	<input checked="" type="checkbox"/> FRI (Final Random Inspection)	<input type="checkbox"/> DPI (During Production Inspection)	<input type="checkbox"/>		

P/O No.	Item No.	Order Qty.(pcs)	Shipment Qty.: (pcs)	Sales destination	Carton Qty.:(ctns)	Inspected Qty. (pcs)	Packed CTN (%)	Production (%)	Sample Size
2022099	TCR-106	2532	2532	France	633	2532	100	100	43
2022099	TCR-102	2532	2532	France	633	2532	100	100	43
2022117	TCR-256	2712	2712	France	678	2712	100	100	47
2022118	TCR-256	1712	1712	France	428	1712	100	100	30
2022118	TCR-259	1000	1000	France	250	1000	100	100	17
2022119	TCR-4266	1200	1200	France	1200	1200	100	100	20
Total:		11688	11688	-	3822	11688	-	-	200

INSPECTION RESULT:	<input checked="" type="checkbox"/> PASS <input type="checkbox"/> FAIL <input type="checkbox"/> PENDING due to remarks of:
ON-SITE CC (Construction check) INFORMATION:	<input type="checkbox"/> N/A <input checked="" type="checkbox"/> The On-site CC for this item was performed on 2022-12-12&13&14 as per our report no. 4397049.00-20&21&22 with the result - <input checked="" type="checkbox"/> PASS <input type="checkbox"/> FAIL <input type="checkbox"/> PENDING

A-1) : AQL and Defects Finding

Inspection Sampling Standard Adopted: <input checked="" type="checkbox"/> ISO 2859-1		Nonconformity (defective)			
Inspection Plan:	Single sampling plans for normal Inspection	Critical	Major	Minor	
Inspection Level:	Fixed 200pcs	AQL:	Not Allowed	2.5	4.0
Inspection with:	<input type="checkbox"/> approved sample <input type="checkbox"/> specific check list <input checked="" type="checkbox"/> general check list	Sample Size:	200	200	200
Defect Description					
For item: TCR-256, Sample size: 77pcs					
Stain mark on heating plate				2	
Stain mark on housing				1	
Slight dent mark on housing				2	
For item: TCR-259, Sample size:17pcs					
Slight scratch mark on housing				2	

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.



Report No.: 4397049.01-23

Report Date: 2022-12-15

This is to supersede our report 4397049.00-23 issued on 2022-12-15

A-3: Picture with description for Remarks.	
NIL	
1.	2.

Inspected by	:	Frank Lu	Signature	:	<i>Frank</i>
Reviewed by	:	Sanky Liu	Signature	:	<i>Sanky Liu</i>

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.



Report No.: 4397049.01-23

Report Date: 2022-12-15

This is to supersede our report 4397049.00-23 issued on 2022-12-15

B. Quantity/Specification/Product requirement verification

B-1) Check inspection lot size against:

<input checked="" type="checkbox"/> Purchase order	<input checked="" type="checkbox"/> Conformed	<input type="checkbox"/> Not conformed
<input checked="" type="checkbox"/> Inspection booking form	<input checked="" type="checkbox"/> Conformed	<input type="checkbox"/> Not conformed
<input type="checkbox"/> Packing list	<input type="checkbox"/> Conformed	<input type="checkbox"/> Not conformed

B-2) Check product description/ colour /style against:

<input checked="" type="checkbox"/> Purchase order	<input type="checkbox"/> Conformed	<input checked="" type="checkbox"/> Not conformed
<input type="checkbox"/> Product specification	<input type="checkbox"/> Conformed	<input type="checkbox"/> Not conformed
<input type="checkbox"/> Reference artwork	<input type="checkbox"/> Conformed	<input type="checkbox"/> Not conformed
<input type="checkbox"/> Golden sample	<input type="checkbox"/> Conformed	<input type="checkbox"/> Not conformed
<input type="checkbox"/> (others: please specify the sender and receiving date)	<input type="checkbox"/> Conformed	<input type="checkbox"/> Not conformed

B-3) Packing material

Export carton	New export carton	<input checked="" type="checkbox"/>
Fasting	Metal staples	<input type="checkbox"/>
Sealing	Transparent gummed tape	<input checked="" type="checkbox"/>
	Opaque gummed tape	<input type="checkbox"/>
	Paper tape	<input type="checkbox"/>
Strapping	Nylon	<input type="checkbox"/>
Material	Ply of cardboard	<input type="checkbox"/> 3ply (single wall) <input checked="" type="checkbox"/> 5ply (double wall) <input type="checkbox"/> 7ply (triple wall)
Others	Poly foam inside packing	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

B-4) Packaging information

	Qty per selling unit	Carton size (cm)			N.W. (kg)	G.W. (kg)
		L(cm)	W(cm)	H(cm)		
For TCR-106,TCR-102						
Gift Box	1	24	24	21	1.514	1.772
Outer carton	4	50	24	44	7.061	7.643
For TCR-256,TCR-259						
Gift Box	1	29	29	26	2.406	2.7
Outer carton	4	59.5	29	54	10.86	11.705
For TCR-4266						
Gift box	1	41	41	30	4.622	5.468

B-5) Barcode check

Overall result: <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> N/A (no barcodes were found on product or packing.)	
1.	Barcode scanning performed on (S-1) : 5pcs
2.	Barcode readability result: <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail
Barcode scanner brand and model number:Eclipse,MS5145	

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.



Report No.: 4397049.01-23

Report Date: 2022-12-15

This is to supersede our report 4397049.00-23 issued on 2022-12-15

3.	Barcode number :			
	TCR-106	<input checked="" type="checkbox"/> on gift box:	3760196094708	<input checked="" type="checkbox"/> on carton: 3760196094708
	TCR-102	<input checked="" type="checkbox"/> on gift box:	3760196090984	<input checked="" type="checkbox"/> on carton: 3760196090984
	TCR-256	<input checked="" type="checkbox"/> on gift box:	3760196092124	<input checked="" type="checkbox"/> on carton: 3760196092124
	TCR-259	<input checked="" type="checkbox"/> on gift box:	3760196096450	<input checked="" type="checkbox"/> on carton: 3760196096450
	TCR-4266	<input checked="" type="checkbox"/> on gift box:	3760301554837	<input type="checkbox"/> on carton:
4.	Did the Barcodes on inspected samples conform to specifications/PO requirement: <input type="checkbox"/> Conformed <input type="checkbox"/> Not conformed <input checked="" type="checkbox"/> N/A			

B-6) Shipping marks:

For export carton	front side marks <input checked="" type="checkbox"/>	side marks <input checked="" type="checkbox"/>
For inner box	front side marks <input type="checkbox"/>	side marks <input type="checkbox"/>

B-7) Color / style / material Conform to Golden Sample?

<input type="checkbox"/> Yes
<input type="checkbox"/> No, please see remark
<input type="checkbox"/> N/A, no Golden sample

C. ON-SITE CHECKING

Test performed	Sample size	Result	Comments	
Hi-pot check	200pcs	Pass	1500V, 2s	
Earth continuity check	200pcs	Pass	12V,25A,less than 0,1Ω	
Basic function check	200pcs	Pass	Switch On/Off	
Smell check	200pcs	Pass	No odor smell	
Full function check	13pcs	Pass	According to instruction manual	
Input power consumption	13pcs	Pass	230V~,50Hz	
			TCR-102,TCR-106	390-405W
			TCR-256,TCR-259	865-914W
TCR-4266	1568-1612W			
Internal check	5pcs	Pass	No defect	
Endurance check	5pcs	Pass	230V~ for 4 hours	
Rub check	5pcs	Pass	15s with water, then Hexane for 15s	
Strain relief check	5pcs	Pass	60N or 100N/25times, displacement less than 2mm.	
Power cord length measurement	5pcs	Reference	without plug:	
			TCR-102,TCR-106	97-98cm
			TCR-256,TCR-259	97-98cm
TCR-4266	83-84cm			
Overfilling test	5pcs	Pass	Further 15% of the capacity of the container or 0.25 L, which is greater, poured in steadily for 1 min	

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.



Report No.: 4397049.01-23

Report Date: 2022-12-15

This is to supersede our report 4397049.00-23 issued on 2022-12-15

Application check	5pcs	Pass	Not defect
Stability test	5pcs	Pass	15° inclined plate, not over turn
Thermal fuse check	1pc	Pass	The thermal fuse is cutting off the current when doing a short circuit for temperature limiter
Tape test	5pcs	Pass	3M tapes

D. OTHER INFORMATION

	Please note									
1.	47 Cartons were randomly sampled from the batch of above item subjected for inspection									
2.	<input type="checkbox"/> Selected carton number:									
	TCR-106									
	323	310	602	114	325	134	281	221	261	62
	413	-	-	-	-	-	-	-	-	-
	TCR-102									
	388	580	167	324	313	109	340	91	376	201
	210	-	-	-	-	-	-	-	-	-
	TCR-256									
	119	220	593	221	175	594	611	149	91	610
	73	24	-	-	-	-	-	-	-	-
	198	357	180	254	280	400	105	51	-	-
	TCR-259									
	9	208	194	228	22	-	-	-	-	-
	TCR-4266									
	-	-	-	-	-	-	-	-	-	-
3.	<input type="checkbox"/> Carton no. was not assigned.									

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.



Report No.: 4397049.01-23

Report Date: 2022-12-15

This is to supersede our report 4397049.00-23 issued on 2022-12-15

E. Critical component data

	Component	Trade Mark	Model	Technical data	Conformity mark	Results
For TCR-256,TCR-259:						
1.	Plug	Not identified	YX301	16A 250V~	VDE	Pass
2.	Power cord	YEXING	H05VV-F	3x0.75mm ²	VDE	Pass
3.	Thermal link	Not identified	RY-216	Tf216°C 250V~ 10A	VDE	Pass
4.	Power switch	BEVAN	BR13	12(4)A,250V	TUV	Pass
5.	Warning element	Not identified	Not identified	220-240V 40W	Test with appliance	Pass
6.	Heating element	Not identified	Not identified	220-240V 900W	Test with appliance	Pass
7.	Magnetic temperature limiter	Not identified	Not identified	Tf155°C	Test with appliance	Pass
8.	Temperature limiter	Not identified	Not identified	Not identified	Test with appliance	Pass

	Component	Trade Mark	Model	Technical data	Conformity mark	Results
For TCR-106,TCR-102						
1.	Plug	Not identified	YX301	16A 250V~	VDE	Pass
2.	Power cord	YEXING	H05VV-F	3x0.75mm ²	VDE	Pass
3.	Thermal link	Not identified	AF192C	Tf192°C 250V~ 10A	TUV	Pass
4.	Power switch	BEVAN	BR13	12(4)A,250V	TUV	Pass
5.	Warning element	Not identified	Not identified	220-240V 40W	VDE	Pass
6.	Heating element	Not identified	Not identified	220-240V 400W	VDE	Pass
7.	Magnetic temperature limiter	Not identified	Not identified	Tf145°C	Test with appliance	Pass
8.	Temperature limiter	Not identified	Not identified	Not identified	Test with appliance	Pass

	Component	Trade Mark	Model	Technical data	Conformity mark	Results
For TCR-4266						
1.	Plug	Not identified	YX301	16A 250V~	VDE	Pass
2.	Power cord	YEXING	H05VV-F	3x1.0mm ²	VDE	Pass
3.	Thermal link	SHENGPING	SPF-214H	Tf216°C	VDE	Pass

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.



Report No.: 4397049.01-23

Report Date: 2022-12-15

This is to supersede our report 4397049.00-23 issued on 2022-12-15

				250V~ 16A		
4.	Power switch	BEVAN	BR23	16(4)A,250V	TUV	Pass
5.	Thermostat	Not identified	KST 101-B	10A 250V	VDE	Pass
6.	Heating element	Not identified	Not identified	220-240V 1600W	Test with appliance	Pass
7.	Magnetic temperature limiter	Not identified	Not identified	Tf157°C	Test with appliance	Pass
8.	Temperature limiter	Not identified	Not identified	Not identified	Test with appliance	Pass

Remark: Above components are tested against CDF under SGS-CSTC Shunde Branch, test report#: GZES220400581402A1.

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

Report No.: 4397049.01-23

Report Date: 2022-12-15

This is to supersede our report 4397049.00-23 issued on 2022-12-15

F. Pictures



1. Warehouse
For TCR-106



2. Warehouse



3. Carton



4. Shipping mark



5. Side mark



6. Barcode

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



7. Opened carton



8. Gift box



9. Gift box



10. Gift box



11. Gift box



12. Artwork

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



13. Artwork

14. Artwork



15. QR code

16. Barcode and production code



17. Artwork

18. Guarantee part

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.


This is to supersede our report 4397049.00-23 issued on 2022-12-15



19. Opened gift box



20. Packing



21. Warning on PE bag



22. Accessories




23. IM



24. Leaflet-1

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



25. Leaflet-2



26. Accessories



27. Marking



28. Marking



29. Appliance



30. Appliance

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



31. Appliance



32. Appliance



33. Appliance



34. Appliance



35. Appliance



36. Appliance

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



37. Marking



38. Control panel



39. Switch



40. Plug



41. Supply cord



42. Cord entrance

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

Report No.: 4397049.01-23

Report Date: 2022-12-15

This is to supersede our report 4397049.00-23 issued on 2022-12-15



43. Rating label
For TCR-102



44. N/A



45. Carton



46. Shipping mark



47. Side mark



48. Barcode

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



49. Opened carton



50. Gift box



51. Gift box



52. Gift box



53. Gift box



54. Barcode and production code

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15




55. Guarantee part



56. Opened gift box



57. Packing



58. Accessories



59. Appliance



60. Appliance

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



61. Appliance



62. Appliance



63. Appliance



64. Appliance



65. Appliance



66. Control panel

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.


This is to supersede our report 4397049.00-23 issued on 2022-12-15




67. Switch




68. Internal view



69. Internal view



70. Internal view




71. Internal view



72. Internal view

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.


This is to supersede our report 4397049.00-23 issued on 2022-12-15



73. Internal view



74. Temperature limited



75. Temperature limited



76. Internal view



77. Thermal fuse



78. Switch

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

Report No.: 4397049.01-23

Report Date: 2022-12-15

This is to supersede our report 4397049.00-23 issued on 2022-12-15



79. Heating element



80. Heating element



81. Magnetic temperature limited
For TCR-256



82. Keep warm element



83. Carton



84. Shipping mark

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



85. Side mark



86. Barcode



87.



88.



89. Opened carton



90. Gift box

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



91. Gift box



92. Gift box



93. Gift box



94. Artwork



95. Artwork



96. Artwork

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15

 <p>POSITIVE TECHNOLOGY</p> <p><i>Cuiseur riz</i></p> <ul style="list-style-type: none"> ✓ Capacité 2,5L ✓ Cuve amovible anti-adhérente ✓ Couvercle en verre ✓ Poignées isolantes ✓ Sélecteur à 2 Positions: <ul style="list-style-type: none"> - Chauffe - Maintien au chaud ✓ Témoin de cuisson ✓ Témoin de chauffe plat ✓ Alimentation 220-240V- 50-60Hz ✓ Puissance 900W ✓ Interrupteur Marche/Arrêt <p>Fourni avec Spatule et Verre Mesureur</p>	 <p>220-240V- 50-60Hz</p> <p>900W ✓ Interrupteur Marche/Arrêt</p> <p>atule et Verre Mesureur</p> <p>Techwood</p> <p>PALMARES Capital avec statuts 5</p> <p>MEILLEURES MARQUES POUR LA MAISON "Cuiseurs à riz"</p> 
<p>97. Artwork</p>  <p>Techwood</p> <p>TCR-256</p> <p>www.techwood.fr</p>	<p>98. Artwork</p>  <p>techwood</p> <p>CUISEUR RIZ</p> <p>العلامة طاهي الأرز مستورد من طرف ش ذ م م الكترول مينو التعاونية العقارية الجامعية قطعة 91 قسم 33 مجموعة ملكية 07 القبة الجزائر الهاتف: 0560.05.47.57 بلد المنشأ: الصين أصل العلامة: فرنسية</p> <p>3 760196 092124</p>
<p>99. QR code</p>  <p>FR</p> <p>ÉLÉMENTS D'EMBALLAGE + NOTICES</p> <p>BAC DE TRI</p> <p>PRODUCTION N° KIS-783</p> <p>PHOTOS NON CONTRACTUELLES</p>	<p>100. Barcode</p>  <p>BON DE GARANTIE Cuiiseur riz électrique TCR-256</p> <p>Date d'achat :</p> <p>Cachet du revendeur</p> <p>FR</p> <p>Cet appareil et ses accessoires se recyclent</p> <p>À déposer en magasin À déposer en déchèterie</p> <p>Points de collecte sur www.qualitecoteconsommateurs.fr</p> <p>Privilégiez la réparation ou le don de votre appareil !</p>
<p>101. Production code</p>	<p>102. Guarantee part</p>

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.


This is to supersede our report 4397049.00-23 issued on 2022-12-15



103. Opened gift box




104. Packing



105. Warning on PE bag



106. Accessories




107. IM



108. Leaflet-1

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



109. Leaflet-2



110. Accessories



111. Marking



112. Marking



113. Appliance



114. Appliance

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



115. Appliance



116. Appliance



117. Appliance



118. Appliance



119. Appliance



120. Appliance

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



121. Marking



122. Control panel



123. Switch



124. Plug



125. Supply cord



126. Cord entrance

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

Report No.: 4397049.01-23

Report Date: 2022-12-15

This is to supersede our report 4397049.00-23 issued on 2022-12-15

 <p>CUISEUR RIZ Techwood® 33 av de Tassigny <small>POSITIVE TECHNOLOGY</small> 94120 Fontenay Sous Bois France RC22A-KY1 TCR-256 220-240V~ 50/60Hz 900W MADE IN P.R.C. - NE PAS IMMERGER KIS-783</p> <p>Icons: Fork and knife, No open flame, Recycled, CE, No water immersion.</p>	
<p>127. Rating label For TCR-259</p>	<p>128. N/A</p>
 <p>SoTech Ref: TCR-259</p>	 <p>SoTech Ref: TCR-259 PRODUCTION NO: KIS-783 Type : RC22A-KX1 C/ 228 /250 BARE CODE 3 760196 096450</p>
<p>129. Carton</p>	<p>130. Shipping mark</p>
 <p>ORDER N° ORDER NO: 2022118 Ref: TCR-259 4 Pcs POIDS BRUT (GW) 11.53 Kg POIDS NET (NW) 9.12 Kg DIMENS. (MEAS) 59.4x30.1x53.2CM</p> <p>Icons: Fragile, Keep Dry, Recycled, CE, No open flame.</p>	 <p>BARE CODE 3 760196 096450</p>
<p>131. Side mark</p>	<p>132. Barcode</p>

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



133. Opened carton



134. Gift box



135. Gift box



136. Gift box



137. Gift box




138. Barcode

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



139. Barcode



140. Production code




141. Guarantee part



142. Opened gift box



143. Packing



144. Accessories

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



145. Appliance



146. Appliance



147. Appliance



148. Appliance



149. Appliance



150. Appliance

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15




151. Control panel




152. Internal view



153. Internal view



154. Internal view



155. Internal view




156. Internal view

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.


This is to supersede our report 4397049.00-23 issued on 2022-12-15



157. Internal view




158. Internal view




159. Internal view



160. Temperature limited



161. Temperature limited



162. Internal view

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



163. Thermal fuse



164. Switch



165. Heating element



166. Heating element



167. Magnetic temperature limited



168. Keep warm element

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



169. Painting free
For TCR-4266



170. Rating label



171. Gift box



172. Gift box



173. Gift box





174. Gift box

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.




175. Artwork

176. Artwork



177. Artwork

178. Artwork



179. Artwork

180. Artwork

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15

	
<p>181. QR code</p>	<p>182. Barcode</p>
	
<p>183. Barcode and production code</p>	<p>184. Artwork</p>
	
<p>185. Guarantee part</p>	<p>186. Opened gift box</p>

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.


This is to supersede our report 4397049.00-23 issued on 2022-12-15



187. Packing




188. Accessories



189. Im



190. Leaflet-1



191. Leaflet-2



192. Accessories

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



193. Marking



194. Marking



195. Appliance



196. Appliance



197. Appliance



198. Appliance

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



199. Appliance




200. Detail



201. Appliance



202. Appliance



203. Appliance



204. Marking

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



205. Control panel



206. Warning logo




207. Switch



208. Rating label



209. Plug




210. Supply cord

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15




211. Internal view




212. Internal view




213. Internal view



214. Internal view




215. Internal view




216. Internal view

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.


This is to supersede our report 4397049.00-23 issued on 2022-12-15




217. Internal view



218. Temperature limit



219. Temperature limit



220. Internal view









221. Thermal fuse



222. Heating element

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15

	
<p>223. Heating element</p>	<p>224. Magnetic temperature limit</p>
	
<p>225. Thermostat</p>	<p>226. Switch</p>
	
<p>227. Painting free</p>	<p>228. N/A</p>

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15

Test and defects



229. Hi-pot / earth resistance test

230. Hi-pot / earth resistance test and power consumption measurement



231. Function check

232. QR code check



233. Rub check


234. Cord length measurement

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



235. Endurance check



236. Stability check



237. Application check



238. Application check



239. Thermal fuse check



240. Thermal fuse check

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



241. Tape check



242. Strain relief check



243. Smell check



244. Over filling check



245. Stain mark on heating plate



246. Stain mark on heating plate

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.

This is to supersede our report 4397049.00-23 issued on 2022-12-15



247. Stain mark on housing



248. Slight dent mark on housing



249. Slight dent mark on housing



250. Slight scratch mark on housing



251. Slight scratch mark on housing



252. Scratch mark on heating element

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.


This is to supersede our report 4397049.00-23 issued on 2022-12-15



253. Slight dent mark on housing



254. Poor painting on housing



255. Slight dent mark on housing



256. Finger mark on lid

-END OF REPORT-

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment. This report is not used for social proof function in China market.